


CT 2 SLAB ASSEMBLY INSTRUCTIONS



PARTS LIST

3"X5" MOUNTING PLATE	4
8X1 FLAT QUAD WS	33
1/4-20X16M CONNECTOR	4
BOLT HEX(4) 1/4-20X60MM	4
ALLEN KEY 4MM	1
CT SLAB ASSEMBLY INSTR	1

