



HEAVY-DUTY MOBILE WORKSTATION – Assembly Instructions

Tools Required:



Adjustable wrench



Phillips Screwdriver

Parts Key




1 x44
M8x16mm





2 x16
M8x55mm




3 x16




4 x1




A (1PC)




B (2PCS)




C (1PC)




D (2PCS)




E (1PC)



F (2PCS)



G (1PC)



H (4PCS)

